

# **THE STANTON HOUSE**

**Addendum to the  
HISTORIC STRUCTURE REPORT:  
THE NORTH AND EAST WINGS**

**Women's Rights National Historical Park  
Seneca Falls, NY**

By  
Kristen Brennan, M.A. HPP  
December 2002

## I.

## LIST OF FIGURES AND CREDITS

Figure 1.“Map of Test Units from Hsu and Towle’s 1983 and 1988 excavations,” from Griswold & Dimmick, p.5.

Figure 2. “Map of Griswold’s 1998 excavations,” from Griswold, p.21.

Figure 3. “Test Unit Locations,” Steven R.Pendery and William Cooney. “DRAFT. Elizabeth Cady Stanton House, North Wing Excavations, Women’s Rights National Historic Park, Seneca Falls, NY.” November 26, 2002.

Figure 4. “Elizabeth Cady Stanton House Archeological Project Area,” Pendery and Cooney, 2002.

Figure 5. “Elizabeth Cady Stanton House Unit N26 W25.5 Feature 33” and “E.C.S. House Unit N26 W25.5 Features 33 and 34 Depth 2.4” below Datum,” Pendery and Cooney, 2002.

Figure 6. “Sketch of Unit n26 W25.5,” Pendery and Cooney, 2002.

Figure 7. “Overall plan showing the location of features encountered during excavation,” William A. Griswold with a contribution by Barbara Yocum. “Appendix 2: Perimeter Drainage Installation at the Stanton House, Women’s Rights National Historical Park, Seneca Falls, New York.” January 2001.

Figure 8. “Plan of Feature 23,” Griswold, 2001.

Figure 9. “Photograph of perimeter drain excavations, west side of the house,” and “Photograph of drain excavations, east side of the house,” Griswold, 2001.

Figure 10. “Slide of Room 202, taken from room 201 facing north east,” The library of the Women’s Rights National Historical Park, Seneca Falls, NY. 1982-3.

Figure 11. “Stanton House: Conjectural floor plans circa 1847-62,” from Yocum, p.130.

Figure 12. “Hagenman House, 68 South Street, Auburn, NY,” from Ruffner, photo archive.

Figure 13. “Symmetrical volumes with variations in chimney placement,” from Glassie, pg.73.

Figure 14. “James B. Walker House, Ridge, NY,” from Ruffner, photo archive.

Figure 15. “Seneca County Greek Revival,” from Ruffner, photo archive.

Figure 16. “House on the Great Western Turnpike,” from Ruffner, photo archive.

Figure 17. "Dean House, Tompkins County, NY," from Ruffner, photo archive.

Figure 18. "John C. Yawger House, Union Springs, NY," from Ruffner, photo archive.

Figure 19. "Yawger House, One Mile South of Cayuga," from Ruffner, photo archive.

Figure 20. "Abandoned House, One Mile North of Ovid," from Ruffner, photo archive.

Figure 21. "Greek Revival, Sheldrake, NY," from Ruffner, photo archive.

Figure 22. "Beach House, Watkins Glen, NY," from Ruffner, photo archive.

Figure 23. "Square House, Penn Yann, NY," from Ruffner, photo archive.

Figure 24. "Map Showing Structural Features Uncovered in the East Wing," from Hsu and Towle, 1983.

Figure 25. "Overall plan showing the location of features encountered during excavation," William A. Griswold with a contribution by Barbara Yocom. "Appendix 2: Perimeter Drainage Installation at the Stanton House, Women's Rights National Historical Park, Seneca Falls, New York." January 2001.

Figure 26. "Photograph of perimeter drain excavations north side of house," and "Photograph of exposed cistern," Griswold, 2001.

Figure 27. "Photograph of Features 21 and 22," Griswold, 2001.

Figure 28. "Plan of Features 15, 21, 22, 29, and 30," Griswold, 2001

Figure 29. "Photograph of Features 15, 29, and 30," Griswold, 2001.

Figure 30. "Photograph and profile drawing of Feature 24," Griswold, 2001.

Figure 31. "Photograph of Feature 31," and "Plan of Feature 31," Griswold, 2001.




Figure 1. Map of Test Units from Towle and Hsu's 1983 and 1988 excavations




Figure 2. Map of Griswold's 1998 Excavations

NO. WO

EXISTANT  
STAINTON HOUSE  
STRUCTURE

Projected North  
Wings

Summer '02  
TEST PITS  
E.U. N26  
W15.5  
DARUM  
HEIGHT  
 $= -3.36'$

Projected Porch

E.U. N26  
W15.5  
DARUM  
HEIGHT  
 $-3.50'$

VERTICAL CONTROL AT NE CORNER OF UNIT 5 -  
CENTRAL POINT OF EXISTING FRONT DOOR THRESHOLD  
ESTABLISHED AT 0.0' (LIBRARY)

Grid, North  
 $1'' = 5'$

WORK I  
STAINTON HOUSE -  
NORTH WINGS  
TESTING PLAN  
6/11/02 - 6/14/02

Top  
Elizabeth Cady Stanton House  
Bottom  
Blithedale Colony Center House

Figure 3. Excavation Sites 2002




Figure 4.

Top  
Elizabeth Cady Stanton House (Present)

Bottom  
Elizabeth Cady Stanton House Archeological Project Area





Figure 5.

Top

Elizabeth Cady Stanton House Unit N26 W25.5 Feature 33

Bottom

Elizabeth Cady Stanton House Unit N26 W25.5 Features 33 and 34  
Depth 2.40" Below Datum






Figure 6.




Overall plan showing the location of features encountered during excavations.

Figure 7.



Photograph of Feature 23. South view.




Plan of Feature 23.

Figure 8.



Figure 9.

Photograph of perimeter drain excavations, west side of the house. South view.



Photograph of perimeter drain excavations, east side of the house. South view.

Figure 9.



Figure 10. Slide of Room 202. Photographer faces northeast.  
Photo by Barbara Yocum, 1982-3.




Figure 11.




Figure 12. Hagenman House, 68 South Street, Auburn, NY



Greek Revival house.  
Sullivan County,  
New York.  
1968



Greek Revival house:  
the single-wing form.  
Otsego County,  
New York.  
1965




Figure 13. Symmetrical volumes with Variations in Chimney Placement. Glassie, p73.

Figure 14. James B. Walker House, Ridge, NY



Figure 15. Seneca County Greek Revival




Figure 16. House on the Great Western Turnpike





Figure 17. Dean House, Tompkins County, NY






Figure 18. John C. Yawger House, Union Springs, NY



Figure 19. Yawger House, One Mile South of Cayuga

Figure 20. Greek Revival, abandoned. One Mile North of Ovid, NY




Figure 21. Greek Revival, Sheldrake, NY





Figure 22. Beach House, Watkins Glen, NY








Figure 23. Square House, Penn Yan, NY



Area P

East Wing



Key:

- \*\*\*\*\* foundation
- brick paving (interior)
- stone slabs
- brick paving (exterior)
- ||| fieldstone slabs

barrell hoops

Figure 24. Map showing structural features uncovered under the East wing. Towle and Hsu, 1983.





Figure 26.


Photograph of perimeter drain excavations,  
north side of house. East view.



Photograph of exposed cistern (Feature 15). South view.


Figure 26.

Appendix 2:8




Photograph of Features 21 and 22. West view.

Figure 27.



Plan of Features 15, 21, 22, 29, and 30.

Figure 28.



Photograph of Features 15 and 29. West View

Figure 29.




Figure 29. Photograph of Features 15, 29, and 30. West View



Photograph of Feature 24. North view .

Figure 30.





Figure 30.



Photograph of Feature 31. West view.



Plan on Feature 31.

Figure 31.